



Copy LT3 T/C

- 1) Lockplates missing
- 2) Stopperbold different
- 3) No label on actuator
- 4) No paint on stud
- 5) Different structure of wheel



MEE LT3 T/C



Copy LT3 T/C

- 1) Different nut
- 2) No paint on ID plate



MEE LT3 T/C

